





ARCADIS RAB Presentation October 23, 2014









This is the story of...

Site 34 (PICA-002) - Former Lower Burning Ground


Also known as: RI Study Area A, (which includes parts of RI Study Area C, Green Pond Brook, Site 180 Waste Burial Area)






Site 34 (PICA-002) Former Lower Burning











- 7 Acre site used for opening burning and 'flashing' of off spec material/debris
- 4 acres of freshwater wetlands
- PAHs, Lead, PCBs, dioxins in soil
- Unacceptable cancer risk and non cancer hazard to human health































What does it take to go from A to B?





1

TIME AND MONEY!

- Time! 24 years
 - Contamination Assessment, Remedial Investigation, Feasibility Study, Proposed Plan, Record of Decision, Explanation of Significant Differences, Remedial Design, Remedial Action Report
- ARCADIS involved the last 8 years
 - Firm Fixed Price Contract for Remediation
 - Over \$1.0M of subcontractor services and material sourced locally
 - Tomco Construction, Rockaway Recycling, B&B Drilling, C&V Paving, GTS Consultants (Surveyors)





PEOPLE!

- 40+ person Army/Govt. Team and Stakeholders: Picatinny (Restoration PM, DPW, Safety, ARDEC, Cultural Resources, Natural Resources, Public Affairs, Legal), Baltimore Dist. COE, New York Dist. COE, Army Environmental Command ERM and Legal, USEPA, NJDEP, RAB Members
- 40+ person ARCADIS Team: engineers, construction workers, environmental scientists, geologist, UXO personnel, ecologists, asbestos specialists, managers, administrative assistants, and contracting support.
 - Millersville, MD; Baltimore, MD; Newtown, PA; Tampa, FL;
 Cranbury, NJ: Edison, NJ; Fair Lawn, NJ; Rochester, NY; Raleigh,
 NC; Kennesaw, GA; Denver, CO.





THE EXPECTED AND UNEXPECTED


- Planning, Ingenuity, Communication, Team Work, Hard Work, Luck, People, Effort....
- 12 acres of unused Army property for wetland mitigation
- What else does it take?
 - A 400 pound 6 inch thick piece of Plexiglas (ingenuity)
 - 3,000 truck trips (effort)
 - Helping a metal recycler understand the red wax inside of munition debris is really red wax (team work and communication)
 - Getting an excavator stuck in a swamp (bad luck, hard work, ingenuity, communication)





The Beginning...

- First documented site activities are in 1960
- First samples collected in 1990, RI in 1998
- Public Meeting 2/19/2004
- Signed ROD in 2005 for 7 acres of asphalt cap
- Army actively used the Site under RCRA permit until 2011








The Middle (part 1)...

- NJDEP classifies
 Green Pond
 Brook as C-1
 waterway
- Riparian zone increases
- SW regulations tighten
- ARCADIS and Army advance idea of hybrid cover









The Middle (part 2)...

- USEPA/NJDEP accept hybrid cap idea, require Explanation of Significant Differences (ESD)
- Contract modification required to comply with new NJDEP regulations
- ESD prepared concurrent with Remedial Design
- Explosive Safety
 Submittal (ESS) required
 (and amended) to handle
 MEC









The End...

- Signed ESD and approved RD in 2014
- Remedial Action Included:
 - Tree clearing on 9 acres before March 31 (to protect endangered Indiana Bat)
 - Surface clearance of all MEC
 - Asbestos abatement, demolition, and removal of 3 buildings
 - Minor subgrading for swale and pond with subsurface MEC clearance
 - 7 acre soil cover (2 ft thick with geotextile layer)
 - 1.5 acre asphalt cap (12 in subbase with 4 in asphalt)
 - 12 acres of wetland mitigation (enhancement)





Site Controls and Erosion and Sediment Controls














Building Demolition













Subbase Preparation



Facing south. Soil cover subbase on left. Bio-Retention pond in background.











Bio-Retention Pond Construction



Bio-Retention pond





UXO Construction Support and Clearance









Beginning Placement of Top Soil July 20, 2014









Beginning Placement of Top Soil July 20, 2014









Wetland Mitigation Plants









=.55:16 AM/5/26/1°

















Wetland Mitigation









Road Repair - 20 Oct 2014



Damage on Shinkle





Shinkle Rd Repairs Oct 2014







The Future...

- Groundwater monitoring,
 Wetland Mitigation
 Maintenance, Land Use
 Controls/Cover Maintenance
- Solar Farm
 - 3,168 Suniva 325 Watt solar panels in the final design with a contract already in-place for 1,786 of those
 - Anticipated Production: 580 kWatt
 DC
 - Ranking system will be ballasted
 - Three inverters











Solar Panel Layout









QUESTIONS?





THANK YOU!

Over 138,000 hours worked 8 Years Over 300 ARCADIANs

26 RAB

Meetings

2 Formal Legal

13 RODs Signed No OSHA recordable injuries **€**

81 Sites with Remedy in Place

(RIP)

Over 90,100 gallons of carbon substrate injected

Analyzed for over 400 unique parameters

Collected over 5,000 samples **€**

1 CNN Special on "Green Remediation" at

5,000+ cy of soil removed from Picatinny

Picatinny m 15+ acres of caps/covers installed

€ 5,972 emails from Ted Gabel (and counting...) €

04:55:16 AM/5/26/1